Posted at: 17:00



4 HOURS OF SPA-FRANCORCHAMPS



REPORT OF THE TECHNICAL DELEGATE

From: The Technical Delegate Report N° 04

To: The Stewards of the Event

CONTROLS AFTER THE QUALIFYING

The following controls have been carried out after the qualifying:

	QUALIFYING				
	LMP2 - 2 cars	LMP2 Pro / Am - 2 cars	LMP3 - 2 cars	LMGT3 - 2 cars	
1	Driver safety equipment	Driver safety equipment	Driver safety equipment	Driver safety equipment	
2	Fuel Sampling	Fuel Sampling	Fuel Sampling	Minimum ground clearance	
3	Fuel out	Fuel out	Fuel out	Fuel Sampling	
4	Car dry weight	Car dry weight	Car dry weight	Fuel out	
5	% front weight distribution	% front weight distribution	% front weight distribution	Car dry weight	
6	Wheel Camber front & rear	Wheel Camber front & rear	Diffuser & Strake (Height, Width, Quantity, Shape)	% front weight distribution	
7	Splitter height	Splitter height	Splitter height	Wheel Camber front & rear	
8	Diffuser & Strake (Height, Width, Quantity, Shape)	Diffuser & Strake (Height, Width, Quantity, Shape)	Skid block thickness	Diffuser & Strake (Height, Width, Quantity, Shape)	
9	Skid block thickness	Skid block thickness	Tape on the bodywork	Rear wing angle	
10	Tape on the bodywork	Tape on the bodywork			
11					
12					
13					
14					
15					
16					
17					
18	Tyre check	Tyre check	Tyre check	Tyre check	
19	Data check	Data check	Data check	Data check	
20	Fuel sample analysis results				

All cars are in compliance on the selected items.

Time: 16.05

Date: 23.08.2025

Antoine CRÉVENAT Technical Delegate

Christian BRUHNKE Technical Delegate

Mr. M. Se

Lucien Monté Technical Delegate